

RoomWizard Firmware 3.5.0 Release Notes

September 29, 2009.

Overview

This document describes updates for Steelcase's RoomWizard firmware version 3.5.0. This release contains several enhancements and bug fixes over the firmware version 3.4.2.

What's New in 3.5.0?

Feature	Description
Enhanced Start Button functionality	The start button now can be activated prior to a meeting start time; this allows the organizer to start a meeting early, and gain access to the room when it is available.
Enhanced Search functionality	Search data is now preserved between searches so the user does not need to re-enter all of the search criteria when making a reservation.
Addition of Network Time Protocol	The RoomWizard now supports Network Time Protocol and eliminates the need for manual time setting of RoomWizards and RoomWizard groups.
Customizable meeting fields.	There customizable text-only fields are available in the Classic Mode Advanced reservation forms options.

Issues Fixed

Version 3.5.0 adds these important fixes as well as many minor fixes to the RoomWizard firmware:

Update	Description
Daylight Savings Time Rules	DST rules have been updated to add more time zones.
Security	Several security updates have been included.
LDAP error checking	The user is warned if LDAP settings are missing.
All day meetings	All day (24hr) meetings are now shown correctly.
Cosmetic Issues	Multiple cosmetic issues have been addressed.

Documentation

Documentation for the RoomWizard is available online at:

<http://www.steelcase.com/roomwizard>

Installing the Update

To update to the latest firmware version from your RoomWizard go to:

1. The RoomWizard home page.
2. RoomWizard Setup.
3. Login as administrator.
4. Choose the Firmware option.
5. Choose the Upgrade option.

6. Click on 'Upgrade This Wizard' for a single unit or 'Upgrade ALL Wizards' for a group of RoomWizards.
7. Click on 'Accept' and wait for the download to complete.
8. Click on 'Perform Upgrade'.

If your RoomWizard unit is running firmware older than version 3.1.8, your unit will do a full disk scan. This process can take up to 25 minutes. Once complete you must check for upgrades again to download the new version 3.5.0.

Known Issues and Release Notes

1. Some usage reports may not download properly if they are too large when using Safari.
2. The upgrade process may be slow compared to previous firmware upgrades because it first performs various pre-upgrade tasks and then proceeds with the regular firmware upgrade to ensure the efficient functionality of the software.
3. The default name of the RoomWizard is "localhost.localdomain." This can cause DNS issues.
4. "Enterprise root CA" certificates will not work as the RoomWizard "trusted root CA certificate." The entry is not in the RoomWizard repository list.

Support:

If you have questions or difficulties with the installation, please call Steelcase Technical Support at: 1.800.334.4922 or send an e-mail to: techsupport@steelcase.com